



22 Traffic Volume Count Location

- **52** The existence of stop bars are not obvious to motorists and pedestrians.
- **182** Pedestrian signals do not exist, providing pedestrians no way to determine what cycle the signal is on.
- **183** Pedestrian signals do not exist, providing pedestrians no way to determine what cycle the signal is on.
- **184** Through traffic on NC has flashing yellow instead of green light.
- **185** Through traffic on Independence has flashing yellow instead of green light.
- **186** No crosswalks along Independence Ave. between these blocks
- **187** Intersection is not fully signalized (7th has stop signs mid-intersection).
- **188** Intersection is not fully signalized (7th has stop signs mid-intersection).
- **189** No pedestrian signals.
- **190** Traffic along North Carolina Avenue between 6th and 8th Street SE does not have sufficient green time to clear the intersections.

Figure 7-16

Potential Transportation Problems 7th Street / 8th Street / Independence Ave / North Carolina Ave SE





Capitol Hill Transportation Study

December 2006

Page 45

